

Step 1: Select a quantity, Q , to minimize or maximize

- Mass (weight), m
- Cost, C

are the most common and the only ones that we will consider